


Note:

1. Sensor is shipped with all dip switches in the OFF position (Factory Default)


TD200 in 3-way
Building Automation, Inc.